







CHAIN IDLER PULLEY REPLACEMENT




CII Part # PN 1717

Concept II © 1995 Concept II, Inc.
MORRISVILLE, VERMONT USA




CHAIN IDLER PULLEY REPLACEMENT

7.




8.



9.




10.




Insert unpatched bolt & turn

11.





12.




CHAIN IDLER PULLEY REPLACEMENT


Replace with Concept II PN 1717



19.




20.




21.




22.




23.



24.



25.



26.

