




Performance Monitor Pickup Replacement




CII Part # PN 1401



1.




2.



3.



4.



5.

Replace with PN 1401

